

## Why should I be thinking about modifying my earth pits?

In most cases earth pits have been installed in such a way that requires the electrode to be disconnected to test. This is time-consuming, can have safety implications and risks remade joints having higher resistance if not refurbished correctly.

Earthing risk management is currently modifying earth pits to make them compatible with a clamp meter tester. This removes the need to identify connections, disconnect or refurbish joints, which completely eliminates any safety issues and drastically reduces test time from 20-35 minutes per pit to approximately 5 minutes.

## EXAMPLE MODIFICATIONS



**BEFORE MODIFICATION**



**AFTER MODIFICATION**



## PHOTOGRAPHS OF MODIFICATIONS



**BEFORE MODIFICATION**



**AFTER MODIFICATION**



## Contact Us

To learn more about earth rod modifications or to arrange an initial assessment to decide if your earth pits are suitable for this modification. Please contact us directly as below:

**Telephone:** 02920 850 444  
**Email:** [info@erm.ltd](mailto:info@erm.ltd)



UVDB Supplier Number: 82961  
Company Number 4582363

